

"Our field at Tyler Junior College was built with a 1% grade running East to West sideline to sideline. Our field has never drained properly in fact with an inch or more of rain in a 24 hour period you could count on not using it for at least 48 hours.

Since the Hydraway system was put in around 4 months ago we have not missed one day on the field. This past month we had 1 period of 3 days with a rainfall total of 5 1/2 inches ending at or around 10:00 am and we could have used the field that night by 5:00pm. We used the field the next night with absolutely no problems. I cannot say enough about your product and could recommend it to anyone without reservation."

Thanks again,
SC

Steve Clements
P.O. Box 9020
Tyler, TX 75711
903 510-2029